



IDAHO DEPARTMENT OF  
HEALTH & WELFARE

C.L. "BUTCH" OTTER – Governor  
RICHARD M. ARMSTRONG – Director

DEBRA RANSOM, R.N., R.H.I.T., Chief  
BUREAU OF FACILITY STANDARDS  
3232 Elder Street  
P.O. Box 83720  
Boise, ID 83720-0036  
PHONE 208-334-6626  
FAX 208-364-1888

February 18, 2009

Rene Stephens, Administrator  
Bitterroot Home  
1411 Falls Avenue East Suite 703  
Twin Falls, Idaho 83301

RE: Bitterroot Home, provider #13G022

Dear Ms. Stephens:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Bitterroot Home, on February 4, 2009.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208)334-6626.

Sincerely,

A handwritten signature in black ink, appearing to read "Eric Mundell". The signature is fluid and cursive.

ERIC MUNDELL, REHS  
Health Facility Surveyor  
Facility Fire Safety and Construction Program

EM/lj

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 02/12/2009  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13G022</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>02/04/2009</b>
NAME OF PROVIDER OR SUPPLIER <b>BITTERROOT GROUP HOME</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>1806 BITTERROOT DRIVE TWIN FALLS, ID 83301</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	<p><b>INITIAL COMMENTS</b></p> <p>The facility is single story, residential Type V(000) construction built in 1992 and is fully sprinklered in habitable spaces. It has a complete fire alarm/smoke detection system. Currently the facility is licensed for 6 ICF/MR beds.</p> <p>The facility was surveyed on February 4, 2009, under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board &amp; Care Occupancies, Impractical Evacuation Capability and 42 CFR 483.470 (j).</p> <p>No deficiencies were cited.</p> <p>The Survey was conducted by:</p> <p>Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety and Construction Program</p>	K 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>13G022</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b> B. WING _____	(X3) DATE SURVEY COMPLETED  <b>02/04/2009</b>
NAME OF PROVIDER OR SUPPLIER  <b>BITTERROOT GROUP HOME</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>1806 BITTERROOT DRIVE TWIN FALLS, ID 83301</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 000	<p>16.03.11 Initial Comments</p> <p>The facility is single story, residential Type V(000) construction built in 1992 and is fully sprinklered in habitable spaces. It has a complete fire alarm/smoke detection system. Currently the facility is licensed for 6 ICF/MR beds.</p> <p>The facility was surveyed on February 4, 2009, under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board &amp; Care Occupancies, Impractical Evacuation Capability, 42 CFR 483.470 (j) and IDAPA 16.03.11 Rules Governing Intermediate Care Facilities for the Mentally Retarded (ICF-MR).</p> <p>No deficiencies were cited.</p> <p>The Survey was conducted by:</p> <p>Eric Mundell REHS Health Facility Surveyor Facility Fire/Life Safety and Construction Program</p>	M 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE